C/015/017 C/015/018 C/015/019 Incoming



Energy West Mining Company P. O. Box 310 15 No Main Street Huntington, UT 84528

JUNE 27, 2011

Mr. Darron Haddock Permit Supervisor 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Dear Mr. Haddock:

I am enclosing for submittal the 2nd. Quarter 2011 Engineering Inspection Reports for Cottonwood/Wilberg/Des Bee Dove Waste Rock Site and the old Waste Rock Site. Also, the Deer Creek Waste Rock Site and Elk Canyon/Original Site are enclosed.

Sincerely,

John Christensen, P.E. Principle Mine Engineer

Encls.

INSPECTION AND CERTIFIED ON EXCESS SPOIL PILE OR			Page 1 of 1			
Permit Number	ACT/015/017/ACT/015/019	Report Date	June 27, 2011			
Mine Name	Cottonwood/Wilberg/Des-B	ee-Dove/Trail Mountain				
Company Name	Energy West Mining Compa	ny				
Excess Spoil Pile or	Pile Name	Cottonwood Waste Rock Site				
Refuse Pile I.D.	Pile Number					
	1211-UT-09-01211-03					
Inspection Date	June 17, 2011					
Inspected By John Christensen/Rick Cullum						
Reason for Inspection 2011 2nd Quarter Inspection						
(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? x No Yes						
Field Evaluation						
Foundation preparation, including the removal of all organic material and topsoil.						
Foundation was prepared according to the approved plan						

undation was prepared according to the approved plan.

Placement of underdrains and protective filter systems.

Not applicable.

Installation of final surface drainage systems.

The out slopes of the containment berms are at their final configuration and have been revegetated. The inlet ditch to the pond has been lined with rip rap and is extended as the pile changes elevation.

Placement and compaction of fill materials.

The Trail Mountain Mine has ceased production. Mine refuse will no longer be hauled to this site. The site will remain active to accommodate future pond cleanings at Trail Mountain and Cottonwood Mines.

Final grading and revegetation of fill.

The outslopes of each containment/lift berm have had final grading and vegetation completed.

Appearances of instability, structural weakness, and other hazardous conditions.

Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

The total storage capacity of the site is a 784,000 cubic yards. The elevation of the current lift varies with the required drainage slope. The surveyed elevation at the center of the active lift is 6,803.31 ft. The final design elevation will be 6,850 ft. The entire site is approximately 36% capacity. The useable area of the present lift is approximately 97%.

C	e	r	t	i	£	i	C	a	t	i	0	n
s	t	a	t	e	m	e	n	t				

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: John Christensen, Sr. Construction Engineer

(Full Name and Title) Signature:

P.E. Number & State:

165651, Utah

RECEIVED

AUG 0 3 2011

Page 1 of 1 Permit Number ACT/015/0017/ACT/015/019 Mine Name Cottonwood/Wilberg/Des-Bee-Dove Company Name Energy West Mining Company Excess Spoil Pile or Refuse Pile Tidentification Inspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection Annual Quarterly or other Seriodic Inspection. Critical Installation, or Completion of Construction Attachments to Report? X No Yes Field Evaluation Poundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Dither Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, total and remaining storage capacity of the structure, evidence of fires in the pile end abatement of the structure affecting its stability or function which has occurred during the per, and any other appear to the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement : hereby certify that; Y an experienced in the construction of earth and rock filis; I am qualified and subtorised in the state of trah the construction of earth and rock filis; I am qualified and subtorised in the state of trah the construction of earth and rock filis; I am qualified and subtorised in the state of trah the construction of earth and rock filis; I am qualified and subtorised in the state of trah the construction of earth and rock filis; I am qualified and subtorised in the state of trah and protection of instability, structural weakness or other h							
Mine Name Company Name Energy West Mining Company Excess Spoil Pile or Refuse Pile Identification Inspection Inspectio				Page 1 of 1			
Excess Spoil Pile or Refuse Pile MSHA ID Number Inspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection Annual, Quarterly or Other Periodic Inspection. Critical Installation, or Completion of Construction) Field Evaluation Poundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill. Site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hasardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and reasoning storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that, I am experienced in the construction of earth and rock fills in a coordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with the certified and approved design and meet or exceed the minimum design requirements under other hazardous conditions of the structure of the structure of the s	Permit Number	ACT/015/0017/ACT/015/019		June 27, 2011			
Excess Spoil Pile or Refuse Pile Identification Tinspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, critical Installation, or Completion of Construction) Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active beaches, total and remaining storage capacity of the structure, evidence of fires in the pile and abstement of such fires, volumes of materials placed in the structure of fires drained in the pile, elevations of active beaches, total and remaining storage capacity of the structure, evidence of fires in the pile and abstement of such fires, volumes of materials placed in the structure and any other appect of the structure, evidence of fires in the pile and advanced to such fires, volumes of materials placed in the structure during the year, and any other appect of the structure feeting its stability of function which are over the pile and accordance with the certified and appearance of earth and rock fills in accordance with the certified and appearance of instability, structural weakness or other hazardous conditions of the structure feeting atability. File Number Bill Number Altalum Altalum Bill Number Bill Number Altalum Bill Second Quarter Inspection Attachments to Rep	Mine Name	Cottonwood/Wilberg/Des-Bee-Dove					
Spoil Pile or Refuse Pile Identification Inspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection (Annual, Quarterly or Other Pariodic Inspection, Critical Installation, or Completion of Construction) Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. Not applicable and toepaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hasardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, total and remaining storage capacity of the structure availability and the structure affecting its stability or function which has occurred during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills, I am qualified and authorized in the structure during the reporting period. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the structure during the reporting period. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the structure during the reporting period. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the structure with approved designs for this structure; that the fill structure has been	Company Name	Energy West Mining	Company				
Refuse Pile Identification Inspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? x No Yes Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other appear appear of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and proved designs for this structure; that the fill structure has been maintained in accordance with approved designs and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any e		Pile Name	Old Waste Rock Site	2			
Inspection Date June 17, 2011 Inspected By John Christensen/Rick Cullum Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? x No Yes Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abacement of the structure affecting its stability or function which has occurred during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that, I am experienced in the construction of earth and rock fills in accordance with the certified and appearance of earth and rock fills in accordance with the certified and approved designs for this structure, that the fill structure has been maintained in accordance with sporved design and meals and the stability, structural weakness or other hazardous conditions of the structure appearances of instability, structural weakness or other hazardous conditions of the structure appearances of the structure appearances of the fill and conditions o	-	Pile Number		G			
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? x No Yes Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with sportowed designs for this structure; that the fill structure has been maintained in accordance with sportowed designs for this structure; that the fill structure has been maintained in accordance with sportowed designs and memory appearances of instability, structural weakness or other havacrous condition	Identification	MSHA ID Number					
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? x No Yes Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with paproved designs for this structure, that the fill structure has been maintained in accordance with paproved designs for this structure, is the she maintained in accordance with approved designs and regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting itsability, By: John Christensen, Sr. Construction Engineer	Inspection Date	June 17, 2011					
Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in he pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure, that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting itsability. By: John Christensen, Sr. Construction E	Inspected By	John Christensen/Ri	ck Cullum				
Field Evaluation Foundation preparation, including the removal of all organic material and topsoil. Constructed according to plan. Flacement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Flacement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other ampect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement Inerby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure, that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer			2011 Second Quarter	Inspection			
Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure of the structu			Attachments to Report?	X No Yes			
Constructed according to plan. Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills, I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved designs for this structure; that the fill structure has been maintained in accordance with approved designs and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer	Field Evaluation			₩/r			
Placement of underdrains and protective filter systems. Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills, I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer			rganic material and topsoil.				
Not applicable. Installation of final surface drainage systems. All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Ottle)							
All surfaces are at their final configuration and drainage established. Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse File structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)							
Placement and compaction of fill materials. This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that, I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure of the structure affecting stability. By: John Christensen, Sr. Construction Engineer			iguration and drained	ro ogtablighed			
This site is complete and at capacity. Final grading and revegetation of fill. Site is complete and vegetation has been established. Appearances of instability, structural weakness, and other hazardous conditions. None Observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)			iguración and dramaç	ge established.			
Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)	This site is comp	plete and at capacity	7.				
Appearances of instability, structural weakness, and other hazardous conditions. None observed. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)			oon ogtablighod				
Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)				_			
instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period. The site will continued to be inspected until MSHA confirms the Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)		and the second s					
Refuse site has been abandoned. Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)	instrumentation, average total and remaining store such fires, volumes of ma	and maximum lifts of materials age capacity of the structure, aterials placed in the structure.	placed in the pile, elevation evidence of fires in the pile e during the year, and any oth	s of active benches, and abatement of er aspect of the			
earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability. By: John Christensen, Sr. Construction Engineer (Full Name and Title)							
	certification State earth and rock fills; I a condition and appearance for this structure; that meet or exceed the minimuregulations; and, that in appearances of instability affecting stability. By: John Christens (Full Name and Title)	m qualified and authorized in of earth and rock fills in acc the fill structure has been made to the fill structure has been made design requirements under all aspections and inspection reporty, structural weakness or otherworks. Sr. Construction En	the State of Utah to inspect a ordance with the certified and intained in accordance with ap 1 applicable federal, state and ts are made by myself and inclir hazardous conditions of the gineer	nd certify the approved designs proved design and d local ude any structure CHRIST			
P.E. Number & State: 165651, Utah	P.E. Number & State:	165651, Utah	REC	FIVE OF UTAH			

	NSPECTION AND CERTIFIED REPORT CESS SPOIL PILE OR REFUSE PILE		Page 1 of 2			
Permit Number	ACT/015/018	Report Date	June 27, 2011			
Mine Name	Deer Creek					
Company Name	Energy West Mining (Company				
Excess	Pile Name Waste Rock Disposal Sit					
Spoil Pile or Refuse Pile	Pile Number					
Identification	MSHA ID Number	1211-UT-09-00121-02				
Inspection Date	Inspection Date June 21, 2011					
Inspected By John Christensen/Rick Cullum						
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)						
	Attachments to Report? X No Yes					

Field Evaluation

1. Foundation preparation, including the removal of all organic material and topsoil.

All construction was done according to the permitted, professional engineered design specifications.

2.Placement of underdrains and protective filter systems.

An under-drain was installed when the site was constructed in 1989. The drain had a small amount of flow coming through it at the time of the inspection.

3.Installation of final surface drainage systems.

All interim slopes are maintained at their proper grade. The final slopes are surveyed to assure they are correct. Also the two final designed rip-rap ditches were installed as per the permitted plan and are extended as more lifts are added.

4. Placement and compaction of fill materials.

The site is leveled as they reach capacity. Trash and extraneous material are removed from the piles shortly after they are placed.

5. Final grading and revegetation of fill.

See No. 3.

The sub-soil berm surrounding the site was seeded shortly after construction. The total capacity of Phase I is 468,215 yd3, this RECEIVED includes both cells 1 and 2.

6.Appearances of instability, structural weakness, and other hazardous conditions.
No weakness or instabilities are evident at this time.

7. Other Comments.

Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

CELL	ELEVATION *	DESIGN ELEV.	CAPACITY**
1 (Upper, northern)	6367.04	6369.2	87%
2 (Lower, southern)	6337.46	6369.2	44%

*The elevations are taken on top of the last compacted lift. The elevation of the dumped piles will not be surveyed until the active lift is compacted and leveled. The survey location is approximately the center of each cell.

** The capacity is based on the last survey elevation compared to available height of waste rock in each cell. To figure the available height an approximate elevation of the original ground was determined based on pre-construction ground contours. The capacity will be updated when a new elevation is survey. The capacity is not based on material hauled to site, as described below.

As of June 1, 2011 there were 7186.47 cu yd3 of material hauled YTD. This estimate is based on invoices from the trucking company of truckloads hauled to the site. Each truckload is assumed to be full at 15 tons and a density of 88 pcf. This estimate could lag actual haul dates by 1 to 3 months, depending of invoicing and accounting.

Certification Statement



I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: John Christensen, Sr. Construction Engineer (Full Name and Tiple)

Signature:

Date: 7/14/11

P.E. Number & State: 165651, Utah

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE					
Permit Number	ACT/015/018	Report Date	June 24, 2011		
Mine Name	Deer Creek				
Company Name	Energy West Mining C	Energy West Mining Company			
Excess Spoil	Pile Name ELK CANYON/ORIGINAL SITE				
Pile or Refuse	Pile Number				
Pile I.D.	MSHA ID Number	1211-UT-09-00121-01			
Inspection Date	June 21, 2011				
Inspected By	John Christensen/Rick Cullum				
Reason for Inspection 2011 2nd Quarter Inspection					
(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction) Attachments to Report? X No Yes					

Field Evaluation

Foundation preparation, including the removal of all organic material and topsoil.

The construction of both sites have been complete for some time in excess of 18 years. The foundations appear to be stable.

Placement of underdrains and protective filter systems.

None

Installation of final surface drainage systems.

The slopes of both sites have no rills, gullies or sloughage present.

Placement and compaction of fill materials.

No fill material is being placed at either site, since both are at their designed capacity. The Elk Canyon site contains approximately 24,000 yd³ original site 90,000 yd3 of fill material.

Final grading and revegetation of fill.

The sites are at capacity. The final grades are established and are re-vegetated.

Appearances of instability, structural weakness, and other hazardous conditions.

None were observed.

Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

There was no coal temporarily stacked at the Elk Canyon pad at the time of inspection.

Certification Statement I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: John Christensen, Sr. Construction Engineer

(Full Name and Title)

Signature:

Date:

7/14/1

No. 165651

P.E. Number & State: 165651, Utah

RECEIVED